

# FINISHING WITH HOT STAMPING FOILS

ONLY FOR LASER-DARK (NO-CUT) A-FOIL & OKI WHITE TONER PRINTERS

### TRANSFER SETTINGS:

	°С∬∘ғ	C	<u>↓</u> ↑
B-PAPER TO A-FOIL	155°C / 310°F	90 sec.	2-3 Bar / 29-43.5 psi / <b>medium pressure</b>
TRANSFER TO TEXTILE	155°C / 310°F	5 - 10 sec.	2 Bar / 29 psi / <b>low pressure</b>
HOT STAMPING FOIL	155°C / 310°F	30 - 45 sec.	5 Bar / 72.5 psi / high pressure



## FINISHING WITH HOT STAMPING FOILS:

#### **PREPARATION OF THE TRANSFER:**

- Print your design using <u>CMYK BLACK</u> (4-Color-Black\*)
- & **Press** with B-Paper (See Table above).
- Separate the B-Paper from the A-Foil while HOT, in a Slow, Low & Fluid Motion.
- Cut around your transfer to remove the coating frame.

#### TRANSFER TO TEXTILE

- Place the transfer on your textile & press together (See Table above).
- Wait until the **textile has completely cooled down**, BEFORE removing the A-Foil!

#### APPLYING THE HOT STAMPING FOIL

- Place the desired sheet of Hot Stamping Foil on your design, cover it with a sheet of Matt Finish Economy & press together (See Table above).
- Wait until the Hot Stamping Foil has completely cooled down, BEFORE removing.
- Wash resistant up to 40°C (Cold Wash Cycle).

**TIP:** Use a textile to rub over the finished design to remove left-over HSF particles! \* 4-Color-Black consists of 100% Cyan, 100% Magenta & 100% Yellow!

ATTENTION: We recommend Swing-Away and Pneumatic Presses! It is important to use heavy pressure for the best results!

